

3M

Hookit™ Finishing Film Discs...



For A Fast Finish.

5 Grades for all your finishing needs—
P600, P800, P1000, P1200 and P1500

À utiliser avec un tampon
à pression (type 05774) ou un
tampon à pression à main
Hookit 3M (P.N. 05774).

Utilisez les produits
de finition 3M
avec soin.
3M France S.A.
11, rue de la
Libération, 92100
Nanterre, France
Tél. (1) 47 33 11 12
Fabrication aux E.-U.

N° de produit
051131-00968
Luzerne
Cote P1200
100 disques
6 po
152mm

3M
Hookit
Disques de
pellicule pour
la finition

Save Time Paint Finishing With...

3M™ Hookit™ Finishing Film Discs are a fast, easy and professional way to sand top coat automotive paints before repainting or compounding. 3M™ Hookit™ Finishing Film Discs cut fast and last long. They are easy to apply and remove from backup pads. And when you get right down to it, that saves you time and money.

- Faster and easier than scuffing or sanding by hand.
- Eliminates the need for cleanup/drying out associated with wet sanding.
- Uniform abrasive grit size produces a consistent finish.
- 3M™ Hookit™ Finishing Film Discs attach firmly to backup pads and can be reused.
- High-strength film backing makes for easy handling.
- Durable bonding system increases disc life.
- Improved 3M™ Fre-Cut™ coating increases disc life.
- 100 discs per box, 4 boxes per case... save money and space.
- The 3M™ Hookit™ Soft Interface Pad allows the 3M™ Hookit™ Finishing Film Disc to be run completely flat—reducing tool vibration.


Choose From Five Grades Depending Upon Your Application



GRADE P600



GRADE P800




GRADE P1000



GRADE P1200



GRADE P1500




Grade P600—Preparing Panels for Sealer and Top Coats.

Recommended for sanding OEM painted panels prior to full panel painting, applying sealer, base coat and clear coat to the entire panel.

3M™ Hookit™ Soft Interface Pad

The 3M™ Hookit™ Soft Interface Pad is made of a soft foam. When used with a 3M™ Hookit™ Backup Pad, it increases conformability, allowing the technician to follow contours and get in closer to most edges. To match the OEM surface texture while removing surface defects, use 3M™ Hookit™ Finishing Film with the 3M™ Hookit™ Soft Interface Pad. 3M™ Hookit™ Finishing Film will level a surface best when used directly on the 3M™ Hookit™ Backup Pad.


3M™ Hookit™ Finishing Film Discs



Grades P800* & P1000*— Preparing the Blend Area.

Recommended for sanding OEM painted panels prior to spot or blend-type painting. Sand scratch can be filled with clear coat.

NOTE: For scuffing blend areas, use with the 3M™ Hookit™ Soft Interface Pad.



Grades P1000*, P1200* & P1500*— Removing Defects from Top Coats.

Recommended for sanding refinish top coats to remove dust nibs, runs, or excess orange peel before compounding.


NOTE: To match OEM texture, use with the 3M™ Hookit™ Soft Interface Pad.

*IMPORTANT: Because of the aggressiveness of DA sanding, care must be taken not to cut through the top coat (clear coat) on style lines, panel edges or other high spots. Hold the DA flat, turn down the air pressure (slow to medium speed), and sand using very light pressure on the tool. Use of the 3M™ Hookit™ Soft Interface Pad will minimize the risk of cutting through the top coat.





Hold down the hooks on the 3M™ Hookit™ Soft Interface Pad before removing the 3M™ Hookit™ Abrasive Disc. Insert thumb between the abrasive and the interface pad when starting to remove the abrasive, to avoid putting excessive stress on the foam.

3M™ Hookit™ Abrasive Disc
3M™ Hookit™ Soft Interface Pad

3M™ Hookit™ Backup Pad



RECOMMENDED REPAIR PROCEDURE FOR 3M™ HOOKIT™ FINISHING FILM DISCS

PAINT CONDITION	PAINT FINISHING			
	STEP 1 TOP COAT SANDING	STEP 2 COMPOUNDING	STEP 3 MACHINE GLAZING	STEP 4 HAND GLAZING
Orange Peel Dust Nibs Paint Runs or Sags Acid Rain Pitting	3M™ Hookit™ Finishing Film Discs 3M™ Hookit™ Soft Interface Pad, 6 in.  05774 P1000 00969 P1200 00968 P1500 00950	3M™ Hookit™ SBS™ Plus Compounding Pad 3M™ Superbuff™ Buffing Pads 3M™ Perfect-It™ II Rubbing Compound  05973 05974 05711 05700 05701	3M™ Perfect-It™ Foam Polishing Pad Glaze 3M™ Perfect-It™ Foam Polishing Pad 3M™ Hookit™ SBS™/Perfect-It™ Backup Pads  05725 05995 05996 05717 05718	3M™ Perfect-It™ Hand Glaze 3M™ Perfect-It™ Wax and Glaze Wipe  06009 05997
Sanding Prior to Paint Finishing P800 recommended for sanding OEM painted panels prior to spot or blend type painting. P600 recommended for sanding OEM painted panels prior to full panel painting.				

3M™ Hookit™ Finishing Film Discs

Part No.	Grade	Size	Discs/Box	Boxes/Case
00951	P1500	5 in.	100	4
00952	P1200	5 in.	100	4
00953	P1000	5 in.	100	4
00954	P800	5 in.	100	4
00955	P600	5 in.	100	4
00950	P1500	6 in.	100	4
00968	P1200	6 in.	100	4
00969	P1000	6 in.	100	4
00970	P800	6 in.	100	4
00971	P600	6 in.	100	4

3M™ Hookit™ Finishing Film Discs—Dust Free

Part No.	Grade	Size	Discs/Box	Boxes/Case
01051	P1500	5 in.	100	4
01052	P1200	5 in.	100	4
01053	P1000	5 in.	100	4
01054	P800	5 in.	100	4
01055	P600	5 in.	100	4
01050	P1500	6 in.	100	4
01068	P1200	6 in.	100	4
01069	P1000	6 in.	100	4
01070	P800	6 in.	100	4
01071	P600	6 in.	100	4

3M™ Hookit™ Soft Interface Pad

Part No.	Size	Pads/Bag	Bags/Case
05773	5 in.	1	10
05774	6 in.	1	10

3M™ Hookit™ Backup Pad

Part No.	Size	Pads/Case
05775	5 in.	10
05776	6 in.	10

3M™ Hookit™ DF* Low Profile Backup Pad

Part No.	Size	Pads/Case
05855	5 in.	10
05856	6 in.	10

*Dust-free

3M™ Hookit™ Hand Pad for 6 in. 3M™ Hookit™ Discs

Part No.	Pads/Bag	Bags/Case
05791	1	20

3M™ Hookit™ Half Round Pad for 6 in. 3M™ Hookit™ Discs

Part No.	Pads/Bag	Bags/Case
05792	1	20

3M™ Hookit™ SBS™ Pad/Backup Pad

Part No.	Description	Pads/Bag	Bags/Case
05711	3M™ Hookit™ SBS™ Plus Compounding Pad	1	24
05717	3M™ Hookit™ SBS™ Backup Pad	1	1

3M™ Superbuff™ Buffing Pads

Part No.	Description	Pads/Bag	Bags/Case
05700	3M™ Superbuff™ Buffing Pad	1	24
05701	3M™ Superbuff™ 2 Plus 2 Pad	1	24

3M™ Perfect-It™ Foam Polishing Pad/Backup Pad

Part No.	Description	Pads/Bag	Bags/Case
05725	3M™ Perfect-It™ Foam Polishing Pad	2	12
05718	3M™ Perfect-It™ Backup Pad – for use on 3M™ Superbuff™ Adaptor #05710	1	1

3M™ Perfect-It™ II Rubbing Compound

Part No.	Description	Unit Size	Qty./Case
05973	3M™ Perfect-It™ II Rubbing Compound	1 qt.	12 qts.
05974	3M™ Perfect-It™ II Rubbing Compound	1 gal.	4 gals.

3M™ Perfect-It™ Glazes/Wipes

Part No.	Description	Unit Size	Qty./Case
06050	3M™ Perfect-It™ Foam Polishing Pad Glaze/Dark	12 oz.	6
06051	3M™ Perfect-It™ Foam Polishing Pad Glaze/Light	12 oz.	6
05995	3M™ Perfect-It™ Foam Polishing Pad Glaze/Light	1 qt.	12 qts.
05996	3M™ Perfect-It™ Foam Polishing Pad Glaze/Dark	1 qt.	12 qts.
05997	3M™ Perfect-It™ Hand Glaze	1 qt.	12 qts.
06009	3M™ Perfect-It™ Wax and Glaze Wipe	125	4 boxes



Automotive Trades Division

3M Center Building 223-6N-01
St. Paul, MN 55144-1000

*3M, "Perfect-It," "Hookit," "SBS" and "Superbuff" are trademarks of Minnesota Mining and Manufacturing Company.

© 3M 1994 60-4400-5202-9-(5410)JR